Workshop Toolbox Compatible Adapter Matrix

(Drivers and Firmware versions are compatible with Workshop Toolbox version 19.24.27 and newer)

Click on your respective brand below for the corresponding compatible adapter matrix

Mack Trucks

Volvo Trucks

Workshop Toolbox Compatible Adapter Matrix:

Revised: 10/01/2025

WorkshopToolBox (WTB) 19.24.27					Volvo Truck								
				Electrical Sytem	Version 4, VN(4)		Version 3, (VN3)						Version 2
				Vehicle Production	(2024 -)		(2013 to Present)						(2004 - 2012)
Communication Adapter	Current Driver/Firmware	Windows 10 (Pro)	Windows 11 (Pro)	*Adapter Connection Modes*	Vehicle Communication and DTC Readout with Ethernet support	Vehicle Communication and DTC Readout without Ethernet support	Three Channel Communication (ISO-15765, J1939, J1587)	Electric Drive Train vehicles	High Speed Programming	Standard Speed Programming	DTC Viewer – EPA 2010 Vehicles	VCADS Pro Diagnostics	DTC Viewer – EPA 2010 Vehicles
VOCOM 2+ T / 88894400 (Recommended)	v4.10.2.2946	OK	OK	*USB & Wireless*	OK	OK	OK	OK	OK	OK	OK	OK	OK
VOCOM MINI 2+ / 88894320 (Recommended)	v4.10.2.2946	OK	OK	*Wireless*	OK	OK	OK	OK	OK	OK	OK	OK	OK
VOCOM II T / 88894000 (Recommended)	v4.10.2.2946	OK	OK	*USB & Wireless*	OK	OK	OK	OK	OK	OK	OK	OK	OK
VOCOM MINI 88894200	v4.10.2.2946	OK	OK	*Wireless*	NS	OK							
Dearborn DPA IV+	v2.02	OK	OK	*USB*			NS		NS	NS	NS	NS	OK
Dearborn DPA XL	v3.11			*USB*	NS	OK							
Dearborn DPA V (Dual CAN/Quad CAN/Pro)	v5.04	OK	OK	*USB & Bluetooth*	NS	OK			NS				
Nexiq USB-Link 3	v3.2.1.8	OK	OK		OK	OK	OK	OK	OK	OK	OK	OK	OK
Nexiq USB-Link 2	v2.8.1.5	OK	OK	*USB & Wireless/Bluetooth*	NS	OK			NS				
Noregon DLA+ 3.0	v2.0.150	OK	OK	*USB & Wireless*	NS	OK			NS				
Noregon DLA+ 2.0 Wired	v4.1.183	OK	OK	*USB*	NS	OK			NS				
Noregon DLA+ 2.0 Wireless	v4.1.183	OK	OK	*USB & Wireless*	NS	OK			NS				
Noregon DLA+	v4.0.7005.1	OK	OK	*USB*			OK		NS	OK	OK	OK	OK
Noregon DLA+ Wireless	v4.0.7005.1	OK	OK	*USB & Wireless*			OK		NS	OK	OK	OK	OK
Noregon DLA+ PLC	v4.0.6829.2	OK	OK	*USB*			OK		NS	OK	OK	OK	OK

Legend:
= OK
= Not Supported
Pending Change

Workshop Toolbox Compatible Adapter Matrix:

Revised: 10/01/2025

WorkshopToolBox (WTB) 19.24.27

Legend:
- = OK
- = Not Supported
- Pending Change

Communication Adapter	Current Driver/Firmware	Windows 10 (Pro)	Windows 11 (Pro)	Adapter Connection Modes	Pioneer (2024 -) Vehicle Communication and DTC Readout with Ethernet support	Pioneer (2024 -) Vehicle Communication and DTC Readout without Ethernet support	VMAC-IV+ (2013 - 2024) Three Channel Communication (ISO-15765, J1939, J1587)	VMAC-IV+ Electric Drive Train vehicles	VMAC-IV+ High Speed Programming	VMAC-IV+ Standard Speed Programming	VMAC-IV+ DTC Viewer - EPA 2010 Vehicles	VMAC-IV (2002 - 2012) DTC Viewer - EPA 2010 Vehicles
VOCOM 2+ T / 88894400 (Recommended)	v4.10.2.2946	OK	OK	USB & Wireless	OK	OK	OK	OK	OK	OK	OK	OK
VOCOM MINI 2+ / 88894320 (Recommended)	v4.10.2.2946	OK	OK	Wireless	OK	OK	OK	OK	OK	OK	OK	OK
VOCOM II T / 88894000 (Recommended)	v4.10.2.2946	OK	OK	USB & Wireless	OK	OK	OK	OK	OK	OK	OK	OK
VOCOM MINI 88894200	v4.10.2.2946	OK	OK	Wireless	NS	OK	NS	OK				
Dearborn DPA IV+	v2.02	OK	OK	USB						NS	NS	NS
Dearborn DPA XL	v3.11			USB	NS	OK	NS	OK				
Dearborn DPA V (Dual CAN/Quad CAN/Pro)	v5.04	OK	OK	USB & Bluetooth	NS	OK	NS	OK			NS	
Nexiq USB-Link 3	v3.2.1.8	OK	OK		OK	OK	OK	OK	OK	OK	OK	OK
Nexiq USB-Link 2	v2.8.1.5	OK	OK	USB & Wireless/Bluetooth	NS	OK	NS	OK		OK	NS	OK
Noregon DLA+ 3.0	v2.0.150	OK	OK	USB & Wireless	NS	OK	NS	OK			NS	
Noregon DLA+ 2.0 Wired	v4.1.183	OK	OK	USB	NS	OK	NS	OK			NS	
Noregon DLA+ 2.0 Wireless	v4.1.183	OK	OK	USB & Wireless	NS	OK	NS	OK			NS	
Noregon DLA+	v4.0.7005.1	OK	OK	USB						OK	NS	OK
Noregon DLA+ Wireless	v4.0.7005.1	OK	OK	USB & Wireless						OK	NS	OK
Noregon DLA+ PLC	v4.0.0829.2	OK	OK	USB						OK	NS	OK